		Corrow Chast	
BNPM/NCB/MCCP/1123 / 2019-20	BANK NOTE PAPER MILL INDIA PRIVATE LIMITED	Cover Sheet	
	CORRIGENDUM No. 1		
	Design, Manufacture, Supply, Installation, Testing & Commissioning of MCC Panels at BNPM Plant, Mysuru	Sheet 1 of 3	
	CORRIGENDUM NO. 1 DATED 20.03.2020		
	<u>FOR</u>		
	TENDER No.		
BNPM	I/NCB/MCCP/1123/2019-20 DATED 21.02.2020		
	FOR		
Design, Manufacture, Supply, Installation, Testing & Commissioning of MCC Panels at BNPM Plant, Mysuru			
PURCHASER	BANK NOTE PAPER MILL INDIA PRIVATE LIMITED		
MATERIAL	· MCC PANELS		
LOCATION	BNPM PLANT, MYSURU, KARNATAKA		



DNDM (NCD (MCCD /4422	BANK NOTE PAPER MILL INDIA PRIVATE LIMITED	Cover Sheet
BNPM/NCB/MCCP/1123 / 2019-20	CORRIGENDUM No. 1	
	Design, Manufacture, Supply, Installation, Testing & Commissioning of MCC Panels at BNPM Plant, Mysuru	Sheet 2 of 3

1.0 SCOPE OF THIS CORRIGENDUM

1. Details provided in this corrigendum shall override those mentioned in the tender no. BNPM/NCB/MCCP/1123/2019-20 Dated: 21.02.2020

2. Except for details mentioned herein, all other details contained in the tender no. BNPM/NCB/MCCP/1123/2019-20 Dated: 21.02.2020 shall remain unchanged.

3. Due date of bid submission:

Closing date and time for receipt of tenders	31.03.2020; 1430 Hrs.
Time and date of opening of techno-commercial bid	31.03.2020; 1500 Hrs.

4. Inclusions/Clarifications through this corrigendum:

Sl. No.	As per Tender Clause	Action/Clarification incorporated in this Corrigendum
	Section VII - Technical Specifications: {Page	
	no. 33 of 70}	
	4. Core Cutting:	
1	Bidder Queries:	
	(a) Need the thickness of the flooring & also the	
	type of flooring used to consider appropriate	(a) Approx. 300 mm RCC floor wit epoxy flooring
	costing for the Core cutting in the panel room.	
	Section VII - Technical Specifications: {Page	
	<u>no. 33 of 70}</u>	
	10. Technical Specifications - 2. MCCB:	
2	Bidder Queries:	
	(b) Fault level of the MCCB is not provided.	(b) Fault level of the MCCB is 50KA
	Kindly confirm the same	
	(c) Kindly confirm whether MCCB is needed with	(c) Yes, Door mounted rotary handl
	Rotary handle or not	is required
	Section VII - Technical Specifications: {Page	
	<u>no. 33 of 70}</u>	
	10. Technical Specifications – i) Panels – a) Base	
3	Frame & Top Frame and e) Instrument Front Plate:	
	Plate:	
	Bidder Queries:	
	(d) Panel sheet thickness is mentioned as 2mm	(d) Panel sheet thickness will be 2mr
	or 2.5mm. Kindly provide the exact details	



DNDM (NCD (MCCD (1422	BANK NOTE PAPER MILL INDIA	PRIVATE LIMITED	Cover Sheet
BNPM/NCB/MCCP/1123 / 2019-20 CORRIGENDUM No. 1		0.1	
,	Design, Manufacture, Supply, Installation, Testing & Commissioning of MCC Panels at BNPM Plant, Mysuru		Sheet 3 of 3
		Action/Clarificatio	n incorporated

Sl. No.	As per Tender Clause	Action/Clarification incorporated in this Corrigendum
	Section VII - Technical Specifications: {Page	
	<u>no. 33 of 70}</u>	
	10. Technical Specifications – ii) ACB Incomers:	
4	Bidder Queries:	
	(e) ACB fault level is mentioned as 50/65Ka.	(e) ACB fault level is 65KA
	Request the exact data	
	Section VII - Technical Specifications: {Page	
	<u>no. 33 of 70}</u>	
	10. Technical Specifications – vi) Cables:	
5	Bidder Queries:	
	(f) Regarding the cable supply, Please provide a	(f) Cable length shall be rounded to
	round figure for the length by considering	next higher standard drum length.
	tolerance also into account.	

